



FOR USE WITH SINGLE MODE FIBER ONLY
INCLUDED BUT NOT SHOWN

- PROTECTIVE DUST CAP
- PINK EPOXY GUIDE SLEEVE
 - INSERT THE FLAT END OF THE GUIDE SLEEVE INTO THE BACK OF THE CONNECTOR UNTIL IT BOTTOMS OUT AGAINST THE FERRULE
 - USING A SYRINGE, INJECT EPOXY UNTIL A BEAD OF EPOXY PROTRUDES THROUGH THE FERRULE TIP
 - REMOVE EPOXY GUIDE SLEEVE BEFORE INSERTING THE FIBER

FOR INFORMATION ONLY
NOT FOR MANUFACTURING PURPOSES

DRAWING PROJECTION

	NAME	DATE
DRAWN	BAG	11/ FEB/11
APPROVAL	DJ	14/JUL/11

COPYRIGHT © 2011 BY THORLABS

VALUES IN PARENTHESIS ARE CALCULATED AND MAY CONTAIN ROUND OFF ERRORS

THORLABS
www.thorlabs.com

FC/APC CONNECTOR 126µm

MATERIAL	N/A	REV B
----------	-----	-------

ITEM #	30126F1	APPROX WEIGHT	0.007 kg
--------	---------	---------------	----------